

GP-013A SAMPLE REGISTRATION

1 - Permit Name
2 - Select Facility
3 - Permit Type
4 - Permit Procedures
5 - Permit Contacts
6 - Industrial Codes
7 - Attachment Upload
8 - Permit Details
9 - Certification
10 - Payment

Please Note
You may click on a previously visited page (above) to navigate back to that screen.

GP-013A Non-HAP Dry-Cleaning Equipment

Note: The system will log you out after 15 minutes of inactivity. If entering a large amount of data, please click on the Save button periodically to save data and reset the 15 minute timer. From the Certification page, you can use the menu on the left-hand side of the page to return to this screen and add additional data if necessary.

Section B: Reason for Applying (Check one)

Select "Unpermitted" if **all** of the pieces of Equipment covered by this General Permit are existing equipment that were never covered by an air permit, or is new equipment that is going to be installed. Continue to Section C: Equipment Inventory.

Select "Permitted" if **one or more** of the pieces of Equipment covered by this General Permit is existing equipment that is or was covered by an air permit, or new equipment that will replace existing pieces of equipment currently listed on an air permit.

If you are unsure the equipment listed in Section C: Equipment Inventory has ever been issued an air permit, please refer to your [Permit/Certificate Folder](#). The Permit/Certificate Folder contains a list of all permits (General and Preconstruction) at the facility and the equipment included in those permits.

- ☒ Unpermitted (new equipment or existing unpermitted equipment)
☐ Permitted (modification or replacement of existing pieces of equipment currently listed on an effective NJDEP permit)

Select Permitted Equipment

Section C: Inventories

Note: You must fill out all required facility designations and descriptions. Required fields are indicated by an asterisk (*).

Emission Unit Inventory

U NJID #	*Facility Designation
18	

Emission Point Inventory

PT NJID #	*Facility Designation	Remove
55		

Add Emission Point

Emission Point Inventory

PT NJID #	*Facility Designation	Remove
55		

Add Emission Point

Equipment Inventory

Important Note: The Non-HAP Dry-Cleaning machine(s) can use any solvent listed under 'Solvent Description' for the selected option from the 'Non-HAP Solvent' drop-down menu as long as the combined solvent limit of 1,000 gallons per 12-month period is not exceeded. For example, if the "Hydrocarbon" option is selected, the owner is free to use any of the solvents from that option (see option list below). Once you change the solvent for one that is not listed in the permitted option, a new registration GP-013A will be required to be submitted. Below are the solvent options and descriptions:

- Hydrocarbon:** DF-2000, Ecosolv, ShellSol, D60, Caled Hydroclene, Ktex, Clerane, and/or Hydro Advanced
- Siloxane:** Green Earth and/or D5 Solvent
- Propylene Glycol Ethers:** Solvair, Rynex, Impress, and/or Gen-X
- Modified Alcohol/Hydrocarbon:** Sensene
- Acetal:** Solvon K4
- Other:** Specify the specific solvent under 'Solvent Description'

E NJID #	*Facility Designation	*Non-HAP Solvent (See Option List Above)	*Solvent Description	*Associated PT NJID #	*Equipment Make	*Equipment Model	*Capacity (lb./load)	*Installation Date (mm/dd/yyyy)	Remove
58									

Add Equipment

Section D: Potential To Emit

The Non-HAP air contaminant Potential to Emit (PTE) of the dry-cleaning machine(s) at 1,000 gallons of Non-HAP solvent shall be less than 4.25 tons per year.

Save Application

Save and Begin Another

Back to Workspace