DEPARTMENT OF ENVIRONMENTAL PROTECTION DIVISION OF WATERSHED MANAGEMENT

REVISION TO THE MERCER COUNTY AND TRI-COUNTY WATER QUALITY MANAGEMENT PLANS

TAKE NOTICE that on Planning Act, N.J.S.A.58:11A-1 et seq, and the Statewide Water Quality Management Planning rules, N.J.A.C. 7:15-3.5, a revision to the Mercer County and Tri-County Water Quality Management (WQM) Plans was adopted by the Department. This revision updates the digital sewer service area (SSA) mapping to correct minor errors within the mapping so that it is consistent with the appropriate adopted Areawide Water Quality Management Plans (WQMP) and Wastewater Management Plans (WMP) per N.J.A.C. 7:15-3.5(b)1.

Within the Mercer County WQM Planning Area in East Windsor Township, Mercer County a correction has been made to expand the East Windsor MUA (NJ0023787) Sewer Service Area (SSA) to include Block 13, Lots 1.01 (Elementis Specialties) and 1.02 (National Lead) as identified in an amendment submitted on behalf of Viridian Partners, LLC and Hampshire Companies to the Mercer County WQMP adopted January 23, 2009.

Within the Mercer County WQM Planning Area in West Windsor Township, Mercer County a correction has been made to include a Sewage Treatment Plant (STP) whose SSA boundary was previously mapped incorrectly and then erroneously deleted entirely. The BASF (American Cyanamid) STP (NJ0005541) was previously mapped incorrectly and in the course of updating the mapping was erroneously deleted. This correction identifies the SSA boundary as depicted in the West Windsor Township WMP that was adopted April 15, 1999.

Within the Tri-County WQM Planning Area in Florence Township, Burlington County a correction has been made to return areas that were incorrectly identified as DGW Less than 20,000 Gallons Per Day (GPD) to their correct designation as General Service Areas for Wastewater Facilities with Planning Flows Less than 2,000 GPD Which Discharge to Ground Water as stated in the Florence Township WMP adopted June 16, 2006.

Corrections to the SSA attribute table have been made to correct/update the WMP, FACNAME, WMPAGCY and NJDPESFL fields to indicate the appropriate plans, facilities, agencies and NJPDES permitted flow rates.

Lawrence J. Bayer, Director

Division of Watershed Management

Department of Environmental Protection

Systember 21, 2007