



Vehicle Inspection Report

Please Review This Important Information

THIS IS AN OFFICIAL RECORD WHICH MUST BE PRESENTED IF THE VEHICLE IS TO BE REINSPECTED. IF LOST, A DUPLICATE RECORD MAY BE OBTAINED FROM ANY INSPECTION FACILITY OR
["http://www.state.nj.us/mvc/Inspections/VIRReprint.html"](http://www.state.nj.us/mvc/Inspections/VIRReprint.html).

This vehicle must pass inspection by 01/31/2020, or it may be subjected to a fine(s) and/or registration suspension. RETAIN THIS DOCUMENT FOR USE ON REINSPECTION. Questions? Visit NJINSPECTIONS.COM or call the Motorist Hotline at 1-888-NJMOTOR.

FACILITY INFO		VEHICLE INFO	CONTROL INFO	
BAKERS BASIN CIF	VIN:	WDDGF8BB1AF*****	Certificate:	CIF000017201935037087
3200 BRUNSWICK PIKE	Plate:	SAMPLE NJ	Software Version:	20190617-01/01
LAWRENCEVILLE, NJ 08648	Veh. Type:		Date:	12/16/2019
888-656-6867	Year:	2010	Time:	10:18:07 AM
Facility ID: CIF000017	Make:	MERCEDES-BENZ	Inspection Type:	INITIAL
Workstation ID: CL020304	Model:	C-CLASS	Sticker#:	C6667133
	Odometer:	52317		
	Fuel Type:	GASO		
	GVWR:	4672		

FINAL RESULT: FAIL Overall Safety Results: N/A Overall Emissions Result: FAIL Credentials: PASS

This test was performed in conformance with section 207(b) of the Federal Clean Air Act and the Inspection Sticker Date is 12/31/2019.

Primary Emission Test Performed: OBD - FAIL

OBD SYSTEM - DIAGNOSTIC RESULTS

Bulb Check:	PASS	OBD Connector:	PASS	MIL Command Status:	FAIL
Check Engine Light On:	FAIL	OBD Communications:	PASS	Overall Readiness Result:	PASS

OBD SYSTEM - READINESS STATUS

Engine Misfire	READY	Catalytic Converters	READY	A/C Refrigerant	UNSUPPORTED
Fuel System	READY	Heated Catalytic Converters	UNSUPPORTED	Oxygen Sensors	READY
Comprehensive Component	READY	Evaporative System	READY	Oxygen Sensors - Heaters	READY
		Secondary Air Injection	READY	EGR Systems	READY

OBD SYSTEM - DIAGNOSTIC TROUBLE CODES PRESENT:

Total # of codes Present:	1	Individual Codes Present:	P0420
---------------------------	---	---------------------------	-------

Secondary Emissions Test(s) Performed:

TEST	RESULT:
Gas Cap	N/A
Tampering	PASS
Visible Smoke	PASS
Liquid Leak	PASS
Indicator Light	FAIL
Misc. Emissions	PASS

EXPLANATION:

Based on information obtained from the On-Board Diagnostic (OBD) system, this vehicle has failed due to a problem with the pollution control system. To continue with the inspection process, the pollution control system should be repaired and the vehicle reinspected. Fault Codes stored on the OBD system are listed above to assist in repairing the vehicle.

The On-Board Diagnostic (OBD) system detected a catalyst fault. To continue with the inspection process, the catalyst should be repaired, required monitors including the catalyst monitor set, and the vehicle reinspected.

Vehicles that fail the Emissions Inspection may be eligible for warranty coverage for the required repairs. Vehicle manufacturers are required by federal law to provide federally certified vehicles with Emissions Warranties for at least eight (8) years or eighty thousand (80,000) miles and on some California certified vehicles up to fifteen (15) years or one hundred fifty thousand (150,000) miles. Warranty coverage may vary depending upon vehicle make and model year. For further information, please refer to the Emissions Warranty section of the vehicle owner's manual.

Inspector:

JOE INSPECTOR

INL00XXXX



Emissions Repair Data

VIN: WDDGF8BB1AF*****

Plate: SAMPLE

Year: 2010

Make: MERCEDES-BENZ

Model: C-CLASS

Date of Repair:

Repair Facility ID:

Repair Technician ID:

Repair Invoice Number:

Confirmation #:

Facility Stamp Here

*Please present to NJ Certified Emissions Repair Facility for completion