

# Sample for NJ-CERT Course



## Vehicle Inspection Report

### Please Review This Important Information

THIS IS AN OFFICIAL RECORD WHICH MUST BE PRESENTED IF THE VEHICLE IS TO BE REINSPECTED. IF LOST, A DUPLICATE RECORD MAY BE OBTAINED FROM ANY INSPECTION FACILITY OR "<http://www.state.nj.us/mvc/Inspections/VIRReprint.html>".

Your vehicle has PASSED its inspection. The results are summarized in this report. Questions? Visit NJINSPECTIONS.COM or call the Motorist Hotline at 1-888-NJMOTOR.

#### FACILITY INFO

NEWARK CIF  
228 FRELINGHUYSEN AVE  
NEWARK, NJ 07114  
888-656-6867  
Facility ID: CIF000042  
Workstation ID: CL190304

VIN: 5NPE34AF0FH\*\*\*\*\*  
Plate: SAMPL2 NJ  
Veh. Type:  
Year: 2015  
Make: HYUNDAI  
Model: SONATA  
Odometer: 16267  
Fuel Type: GASO  
GVWR: 4497

#### VEHICLE INFO

#### CONTROL INFO

Certificate: CIF000042201934748570  
Software Version: 20190617-01/01  
Date: 12/13/2019  
Time: 01:29:30 PM  
Inspection Type: RETEST  
Sticker#: 1655264

**FINAL RESULT: PASS** Overall Safety Results: N/A Overall Emissions Result: PASS Credentials: PASS

This test was performed in conformance with section 207(b) of the Federal Clean Air Act and the Inspection Sticker Date is 09/30/2021.

#### Primary Emission Test Performed: OBD - PASS

#### Secondary Emissions Test(s) Performed:

TEST	RESULT:
Gas Cap	N/A
Tampering	PASS
Visible Smoke	PASS
Liquid Leak	PASS
Indicator Light	PASS
Misc. Emissions	PASS

#### EXPLANATION:

#### Inspector:

JOE INSPECTOR INL00XXXX